Activity Area:	Walesby Lodge		
Minimum Staffing Level	N/A		
Staff/Pupil Ratio	N/A		
Staff Qualifications	N/A		
Maximum Number of Participants	N/A		
Role of Accompanying Adult:	Controller of building		
	while resident		

Risk Matrix	Likelihood			
Consequences	Very Likely	Likely	Unlikely	Highly Unlikely
Fatality	High	High	High	Medium
	-16-	-15-	-14-	-13-
Major Injuries	High	High	Medium	Medium
	-12-	-11-	-10-	-9-
Minor Injuries	High	Medium	Medium	Low
	-8-	-7-	-6-	-5-
Negligible Injuries	Medium	Medium	Low	Low
	-4-	-3-	-2-	-1-

Hazard	Persons at risk	Prior Risk	Controls Measures	New Risk Factor
Location hazards	Instructors Observers Participants Contractors	High 8	Area kept clear of obstruction, tables and chairs moved back as appropriate.	Medium 6
Vehicle traffic, Car park	Instructors Observers Participants Contractors	High 16	Grounds are to be clear of all obstacles. Residents to be notified of traffic outside main door when leaving. Site speed limits of 5mph. Car park fenced off to avoid children running into traffic.	Medium 13
			Ignition Sources	
Electrical appliances Gas boiler Kitchen equipment Electrical system Smokers materials Arson	Instructors Observers Participants Contractors	High 16	All electrical appliances PAT tested. All Gas appliances serviced every year by LPG Gas Engineer. All fire alarms tested once a month and serviced twice a year. Emergency lighting tested once a month. CCCTV in operation around site and staff resident on site security.	Medium 13
Fuel Sources				
LPG gas supply Cooking oils Cigarette lighters etc. Curtains/ mattresses Sleeping bags/ covers Litter/ waste Chairs/ tables Building materials	Instructors Observers Participants Contractors	High 16	Visitors - 'Visitor Code of Practice' Staff – Site induction/ on-going training. Safety notice/ test certificate. Building maintenance weekly checks. All none COSH chemicals removed.	Medium 13
Building				
Uneven surfaces	Instructors Observers Participants Contractors	High 12	Residents encouraged not to run. Leaders issue warnings with regards to hazardous areas. Safety notices on display in main living room.	Medium 9



Steps entrance and fire exit	Instructors Observers Participants Contractors	High 12	Residents encouraged to walk while using stairs.	Medium 10
Bunk Beds	Participants	High 8	Residents encouraged not to be messing around on beds. Leaders issue warnings with regards to the hazarders of bunk beds.	Medium 6
Showers/hot water taps	Participants Instructors Contractors	High 8	All Gas appliances serviced every year by LPG Gas Engineer. Temperature checks carried out every month and adjustments made where needed.	Low 5
Decking area	Instructors Observers Participants Contractors	High 8	Safety rail in place to stop residents going over the edge. Centre staff observation, and leaders advised of risk. Lighting in area to ensure safe walk way.	Medium 6

Forest 1938

